



Benning Power Plant Demolition Completed

 Pepco Holdings, Inc

July 2015

Benning Power Plant

- Pepco Energy Services has owned and operated Benning Power Plant since 2000
- Plant ceased operation in June 2012
- PES completed demolition of the plant on schedule in spring 2015



Dismantling the Benning Power Plant

- The demolition was carefully planned and executed
 - **Phase 1:** Dismantling of the cooling towers (*September 2013 to December 2013*)
 - **Phase 2:** Demolition of the Benning Power Plant buildings and equipment (*November 2013 to Spring 2015*)
 - **Phase 3:** Site restoration (*Spring 2015*)




Project Facts

- 1,624 truckloads of recycled material
- 5,314 loads of clean backfill (soil) (used in regrading)
- 244 loads of stone (used in regrading)
- 155,455 total manhours
- Zero OSHA recordable accidents

Benefits of Closing and Demolition

- Elimination of air emissions from burning of fuel oil at the power plant
- Elimination of fuel oil storage and oil truck deliveries
- Removal of the visual impact of the power plant and the smoke stacks
- Removal of any hazardous materials in the power plant

Before and After



The Benning Power Plant was located on the westernmost portion of the Benning Service Center at 3400 Benning Road, N.E., in Washington, D.C., where it occupied approximately 25 percent of the facility's 77 acres.



The site of the Benning Power Plant, looking north from Benning Road. The site was regraded as the final step in demolition. The Benning Service Center will remain in use.